NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Thursday, March 21, 2019

SIGNS AT WEST



B609 42

Thursday, March 21, 2019

SIGNS AT EAST



B609 43

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 01, 2016

TOP OF SIDEWALK BRACKET BROKEN



B571 04

Tuesday, November 01, 2016

SIDE VIEW OF SIDEWALK BRACKET



B571 05

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, June 21, 2016

RUST AT FLOOR BEAM EXTERIOR



B561 27

Tuesday, June 21, 2016

RUST AT FLOOR BEAM EXTERIOR



B561 28

Tuesday, June 21, 2016

HOLE IN BRACING



B561 29

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, June 21, 2016

FINE CRACKS IN SOFFIT



B561 30

Tuesday, June 21, 2016

HOLE IN CONNECTION PLATE



B561 31

Tuesday, June 21, 2016

RACCOON ON FLOORBEAM FLANGE



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, June 21, 2016

BEARING AT NORTHWEST



B561 33

Tuesday, June 21, 2016

BEARING AT SOUTHWEST



B561 34

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Thursday, August 14, 2014

CROSS BRACE REPAIR, SECOND BAY FROM EAST.



B506 01

Thursday, August 14, 2014

CROSS BRACE CONNECTION PLATE HOLED, TYPICAL OF SEVERAL.



B506 02

Thursday, August 14, 2014

BOTTOM FLANGE OF EXTERIOR STRINGER, 1/4" REMAINING.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Thursday, August 14, 2014

WEB HOLED UNDER SIDEWALK STRINGER # 1, MIDSPAN.



B506 04

Thursday, August 14, 2014

PACK RUST BETWEEN LOWER CHORD ANGLES.



B506 05

Thursday, August 14, 2014

CROSS BRACING ANGLE HOLED, TYPICAL OF FEW.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Thursday, August 14, 2014

FINE CRACKS IN SOFFIT.



B506 07

Thursday, August 14, 2014

CONNECTOR PLATE REPAIR, FLOORBEAM # 3 AT NORTH.



B506 08

Thursday, August 14, 2014

VERTICAL CRACKS, RUST STAINS, WEST ABUTMENT.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Thursday, August 14, 2014

RUST AND SCALE AT SOUTHWEST BEARING.



B506 10

Thursday, August 14, 2014

JOINT SEAL HOLED AT WEST.



B506 11

Thursday, August 14, 2014

BEARING AT NORTHEAST



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Wednesday, June 25, 2014

PLATED REPAIR AT NORTHEAST BEARING



X009 13

Wednesday, June 25, 2014


ROLLERS MOVING OUT OF POSITION AT NORTHEAST BEARING



X009 14

Wednesday, June 25, 2014

ROLLERS MOVING OUT OF POSITION AT NORTHEAST BEARING



X009 15

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

INTERIOR VIEW OF NORTHEAST ROLLER BEARING.



B456 01

Monday, March 25, 2013

PLATE HOLED AT NORTHEAST ROLLER BEARING.



B456 02

Monday, March 25, 2013

NORTHEAST ROLLER BEARING PLATE RUSTED WITH SECTION LOSS.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

NORTHEAST ROLLER BEARING PLATE RUSTED WITH SECTION LOSS.



B456 04

Monday, March 25, 2013

PLATE HOLED AT NORTHEAST ROLLER BEARING.



B456 05

Monday, March 25, 2013

EXTERIOR SIDE OF NORTHEAST ROLLER BEARING PLATE RUSTED WITH SECTION LOSS.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

EXTERIOR SIDE OF NORTHEAST ROLLER BEARING PLATE RUSTED WITH SECTION LOSS.



B456 07

Monday, March 25, 2013

LOWER LATERAL BRACING CONNECTION BROKEN AT EAST.



B456 08

Monday, March 25, 2013

LOWER LATERAL BRACING CONNECTION PLATE HOLED AT EAST.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

LOWER LATERAL BRACING CONNECTION PLATE HOLED AT EAST.



B456 10

Monday, March 25, 2013

MINOR RUST ON STRINGERS AND FLOOR BEAMS.



B456 11

Monday, March 25, 2013

HOLES IN LOWER LATERAL BRACE AT MIDSPAN.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

PACK RUST IN MIDDLE OF LOWER CHORD AT NORTH.



B456 13

Monday, March 25, 2013

LOWER LATERAL BRACING CONNECTION PLATE HOLED AT BAY 2 AT WEST.



B456 14

Monday, March 25, 2013

LOWER LATERAL BRACING CONNECTION PLATE HOLED AT BAY 2 AT WEST.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

LOWER LATERAL BRACING CONNECTION PLATE AT BAY 2 AT WEST.



B456 16

Monday, March 25, 2013

SOUTHWEST ROLLER BEARING PLATE RUSTED WITH SECTION LOSS.



B456 17

Monday, March 25, 2013

NORTHWEST ROLLER BEARING.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, March 25, 2013

MODERATE RUST AT GUSSET PLATE NEAR NORTHWEST ROLLER BEARING.



B456 19

Monday, March 25, 2013

HEAVY TRAFFIC DAMAGE TO SOUTHWEST RAIL.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, June 19, 2012

BOTTOM SIDEWALK RAIL BROKEN AT MIDSPAN.



B434 37

Tuesday, June 19, 2012

SOUTHWEST RAIL HEAVILY DAMAGED. TYPICAL OF NE AND SE.)



B434 38

Tuesday, June 19, 2012

PLATE HOLED AT NORTHEAST ROLLER BEARING.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Friday, September 09, 2011

SECOND SWAY BRACE FROM EAST BROKEN



B409 26

Friday, September 09, 2011

NORTHEAST BEARING RUSTED



B409 27

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 14, 2008

LATERAL BRACING CONNECTION PLATE HOLED, WEST SIDE OF FLOORBEAM TWO



B332 35

Monday, April 14, 2008

BRIDGE SEAT SPALLED AT STRINGER ONE SOUTHWEST, ANCHOR BOLT EXPOSED.



B332 36

Monday, April 14, 2008

PROTECTIVE WEARING SURFACE COATING PEELING AWAY.



B332 37

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Wednesday, April 09, 2008

CONNECTION PLATE AT NORTHEAST BEARING HOLED



B332 31

Wednesday, April 09, 2008

CONNECTION PLATE AT NORTHEAST BEARING HOLED



B332 32

Wednesday, April 09, 2008

NORTHEAST ROLLER BEARING, SIDE PLATE TIPPED



B332 33

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Wednesday, April 09, 2008

LATERAL BRACING CONNECTION PLATE HOLED, WEST SIDE OF THIRD FLOORBEAM FROM EAST.



B332 34

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, October 16, 2006

PIPE RAIL LOOSE AT NORTHWEST SIDEWALK



B293 05

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 23, 2004

UNDERSIDE VIEW OF NEW SLABS AND TOP FLANGE OF STRINGER WITH HOLES AND FLAME CUTS



B228 04

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Wednesday, October 08, 2003

WEST APPROACH



B189 11

Wednesday, October 08, 2003


WEST APPROACH



B189 12

Wednesday, October 08, 2003

SOUTHEAST ELEVATION



B189 13

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Wednesday, October 08, 2003

SOUTH ELEVATION



B189 14

Wednesday, October 08, 2003

SOUTH ELEVATION



B189 15

Wednesday, October 08, 2003

PRE-CAST DECK PANELS READY FOR INSTALLATION.



B189 16

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 22, 2002

ASPHALT CRACKED AND LOOSE OVER SECTION OF DETERIORATED BRIDGE PLANK.



B146 20

Monday, April 22, 2002

BRIDGE PLANK TORN AND HOLED AT WEST END.



B146 21

Monday, April 22, 2002

ASPHALT SETTLED AND HUMPED UP 3 INCHES, 20 FEET FROM WEST END.



B146 22

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 22, 2002

BRIDGE PLANK TORN AND HOLED AT WEST END, UNDERSIDE VIEW.



B146 23

Monday, April 22, 2002

BOLTS MISSING AT BRIDGE PLANK CONNECTION TO UPPER FLANGE AT EAST END.



B146 24

Monday, April 22, 2002

AREA TOPSIDE OF PREVIOUS PICTURE B146-24.



B146 25

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, January 29, 2002

CRACKED, DEPRESSED, LOOSE AREA IN DECKING (TYP OF SEVERAL AREAS THROUGHOUT BRIDGE)



B141 12

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 27, 2001

CRACKED, DEPRESSED AREA IN ASPHALT TOPSIDE (TYP OF MANY AREAS)



B138 41

NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

WEST APPROACH.



B032 07

Monday, April 19, 1999

SOUTH ELEVATION.



B032 08

Monday, April 19, 1999

DECK CRACKED AND DEPRESSED AT SOUTHWEST END.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

DECK CRACKED AND DEPRESSED AT FLOORBEAM # 3, AT SOUTH.



B032 10

Monday, April 19, 1999


DECK CRACKED AT PATCH OVER FLOORBEAM # 6,AT NORTH.



B032 11

Monday, April 19, 1999

DECK CRACKED, DEPRESSED IN BAY # 6.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

DECK CRACKED, DEPRESSED AT FLOORBEAM # 8.



B032 13

Monday, April 19, 1999

DECK CRACKED, DEPRESSED AT BAY # 8.



B032 14

Monday, April 19, 1999

DECK CRACKED, DEPRESSED AT FLOORBEAM # 10,NORTH.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

DECK CRACKED, DEPRESSED AT FLOORBEAM # 12.



B032 16

Monday, April 19, 1999

DECK CRACKED, DEPRESSED AT FLOORBEAM # 14,NORTH.



B032 17

Monday, April 19, 1999

DECK CRACKED, DEPRESSED, AND PATCHED AT EAST END.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

BRIDGE PLANK HOLED THROUGH OVER FLOORBEAM #2, BAY 2.



B032 19

Monday, April 19, 1999

BRIDGE PLANK LEAKING AT FLOORBEAM #5, BAY 5.



B032 20

Monday, April 19, 1999

RUST AND LEAKING BAY #6.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

TOP FLANGE OF STRINGER #5, WITH SECTION LOSS, IN BAY # 6.



B032 22

Monday, April 19, 1999

TOP FLANGE OF STRINGER #4, WITH SECTION LOSS, IN BAY # 6.



B032 23

Monday, April 19, 1999

BRIDGE PLANK LEAKING IN BAY #8.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

BRIDGE PLANK LEAKING IN BAY #9.



B032 25

Monday, April 19, 1999

BRIDGE PLANK LEAKING IN BAY #10, FLOORBEAM # 9.



B032 26

Monday, April 19, 1999

BRIDGE PLANK LEAKING IN BAY #11.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Monday, April 19, 1999

BRIDGE PLANK LOOSE IN BAY #11.



B032 28

Monday, April 19, 1999

STRINGER #7 CUT, NEAR FLOORBEAM #11.



B032 29

Monday, April 19, 1999

STRINGER #4 AT EAST END BAY.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

DETERIORATED AREA OVER FB#6 @N. W/ FLEX CRACKS & HOLES THROUGH BRIDGE PLANK.



B018 04

Tuesday, November 03, 1998

HOLES THROUGH BRIDGE PLANK @ N . OVER FB#6.



B018 05

Tuesday, November 03, 1998

FLEX CRACKED AREA OF BRIDGE PLANK @ N . OVER FB#6.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

ASPHALT CRACKED & DEPRESSED OVER FB#5 @ SOUTH & BRIDGE PLANK MOVING WITH LOADINGS.



B018 07

Tuesday, November 03, 1998

FLEX CRACKED AREA OF BRIDGE PLANK @ N . OVER FB#6.



B018 08

Tuesday, November 03, 1998

ASPHALT CRACKED OVER FB#7 @ NORTH.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

ASPHALT CRACKED OVER FB#7 @ SOUTH.



B018 10

Tuesday, November 03, 1998

DETERIORATED AREA OVER FB#10 @ CENTERLINE.



B018 11

Tuesday, November 03, 1998

LOOSE BOLTS CUT OUT @ SOUTH OVER FB#4.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

APPEARS TO BE CRACKED WELD @ DIAPHRAGM, BAY#6, BETWEEN STRINGER #4 & #5 @ MIDSPAN. WAS NOT CRACKED WHEN PAINT WAS REMOVED.



B018 13

Tuesday, November 03, 1998

DECK LEAKAGE, BAY#6.



B018 14

Tuesday, November 03, 1998

RUNNING CRACK IN BRIDGE PLANK @ FB#7 @ SOUTH.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

BAY#8, CENTER SPAN



B018 16

Tuesday, November 03, 1998

BAY#1, @ SOUTH W/ DENTS IN BRIDGE PLANK.



B018 17

Tuesday, November 03, 1998 BAY#1, BRIDGE PLANK.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

BAY#2.



B018 19

Tuesday, November 03, 1998

SOUTH WEST END OF DECK @ VT. HAS ONE INCH OF SETTLEMENT.



B018 20

Tuesday, November 03, 1998

NH END HAS SCARIFIED BRIDGE PLANK.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

NH END HAS SCARIFIED BRIDGE PLANK.



B018 22

Tuesday, November 03, 1998

NH END HAS BRIDGE PLANK LEAKAGE.



B018 23

Tuesday, November 03, 1998

NH END HAS A HOLE @ NORTH BEARING.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

NH END HAS A HOLE @ NORTH BEARING.



B018 25

Tuesday, November 03, 1998

NORTH EAST APPROACH RAIL DAMAGE.



B018 26

Tuesday, November 03, 1998

SOUTH WEST APPROACH RAIL DAMAGE @ VT. END.



NH119 over CONNECTICUT RIVER

Owner: NHDOT Inspection Team: B Bridge Maintenance Crew: 7

Tuesday, November 03, 1998

SOUTH WEST BEARING @ STRINGER#1,HAS SPALLED AREA BENEATH IT.

